



A Hanging Mounting


Screw through the hole, rock with screw nut .

1




2


Connect the installation fixture and installation shrapnel by steel cable




4




Installation the fixture



3






Cutout:6.0mm




B Ceiling mounting

1

Screw through the hole, rock with screw nut .




2




Cutout:6.0mm

Fixed the installation shrapnel at the ceiling





4

Installation the fixture



3



Fixed the installation shrapnel at the ceiling

Noted:Pls make sure that the power off before the installation.